

# Oil Field Environmental Incident Summary

**Incident:** 20140717215035      **Date/Time of Notice:** 07/17/2014 21:50

**Responsible Party:** Hiland Partners LP

**Well Operator:** CONTINENTAL RESOURCES, INC.

**Well Name:** CHARLOTTE 2-22H

**Field Name:** BANKS

**Well File #:** 21128

**Date Incident:** 7/17/2014      **Time Incident:** 18:00

**Facility ID Number:**

**County:** MCKENZIE

**Twp:** 152

**Rng:** 99

**Sec:** 22

**Qtr:**

**Location Description:** Spill approximate 50' off the Charlotte well site location on the pipeline Right of Way.

**Submitted By:** Austin Schneider

**Received By:**

**Contact Person:** Steve Jensen  
302 N Independence  
Enid, OK 73701

**General Land Use:** Well/Facility Site

**Affected Medium:** Topsoil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Pipeline Leak

**Release Contained in Dike:** No

**Reported to NRC:** No

	Spilled	Units
Oil	8	Barrels

**Recovered**      **Units**

**Followup**      **Units**

**Brine**

**Other**

**Description of Other Released Contaminant:**

Approximate 8 bbls of Condensate

**Inspected:**

**Written Report Received:** 10/5/2016

**Clean Up Concluded:**

**Risk Evaluation:**

None

**Areal Extent:**

Approximate 1 bbl of condensate on the pipeline Right of Way and 7 bbls of the Right of Way.

**Potential Environmental Impacts:**

Environmental Impacts limited to soil

**Action Taken or Planned:**

Root Cause currently under investigation.

**Wastes Disposal Location:** Soil will be stage within a lined secondary containment awaiting sample analysis

**Agencies Involved:**

**Updates**

---

**Date:** 7/17/2014    **Status:** Reviewed - Follow-up Required

**Author:** Roberts, Kris

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

7/17/14 - 2100 +/- Received call from emergency response phone regarding this incident and returned the call from the company contact. Release is from a 10-inch "condensate" pipeline on the pipeline right-of-way near the Charlotte 2-22H wellsite. Followup is necessary to determine potential impacts and confirm cleanup. Company contact's information is that there is no surface water impacted or in the near vicinity.

---

**Date:** 7/31/2014    **Status:** Inspection

**Author:** Stockdill, Scott

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Arrived on location at 17:00 7/31/2014.

Walked the entire stretch of disturbed soil that is next to the Charlotte 2-22 location. There are no signs of impact to any of the soil. A call will be made to the responsible party ensuring that the contaminant was properly cleaned up.

No more onsite follow up is necessary at this time. More follow up is necessary via phone call.